


# REPORT

## TRUESDAIL LABORATORIES, INC.

CHEMISTS · MICROBIOLOGISTS · ENGINEERS  
RESEARCH · DEVELOPMENT · TESTING  
ESTABLISHED 1931



14201 FRANKLIN AVENUE  
TUSTIN, CALIF. 92680  
(714) 730-6239 • (213) 225-1564  
FAX (714) 730-6462

CLIENT: Douglas Aircraft Company  
Internal Mail Code 74-41  
3855 Lakewood Blvd.  
Long Beach, CA 90846  
ATTN: Boramy Ith

REPORT DATE: January 12, 1994

RECEIVED: December 30, 1993

LABORATORY NUMBER: 65453

Water from Torrance Stormdrain  
Torrance Facility  
P.O. Number: T & M 25998-C

Analysis as Required by NPDES Permit #CA0001414

### RESULTS


Total Flow, GPD  
pH, Units (EPA 150.1)

No Flow  
7.6

### MILLIGRAMS PER LITER

Parameter	Method	Detection Limit	Concentration
Biochemical Oxygen Demand	405.1	2.0	ND
Oil and Grease	413.1	6.0	13.2
Settleable Solids	160.5	0.2	ND
Total Suspended Solids	160.2	4.0	4.0

ND = Not detected, below detection limit.



Respectfully Submitted,  
Truesdail Laboratories, Inc.

Thomas Herrin, Manager  
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.